

1. Approving Competent Authority / Country
CAA.UK

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

2. Form Tracking Number:
W/201911063

4. Organization Name and Address:
Avia Technique Ltd.
Unit 1, 3, 4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom RG41 2QU
Pn: +441189789789, Fax: +441189794511

5. Work Order / Contract / Invoice Number:
W. 01911.63

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
1	Oxygen Cylinder Assembly	891511-14	1.00	C08020076	Overhauled

12. Remarks:
CMM: 35-28-91 Revision: 1

The work identified in Block 11 and described herein has been completed in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. 18QY1893X

Next Overhaul / Hydrostatic Test: 08-2022
Cylinder Life Expiry Date: 12-2031
Avia Technique Ltd have checked and verified that there are no pertinent AD's or SB's relevant.

13a. Certifies that the items identified above were manufactured in conformity to:
 Approved design data and/or in a condition fit for safe operation
 Non approved design data specified in Block 12

14a. Part-145 A.50 Release to Service Other regulation specified in Block 12
 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:	13c. Date (dd/mm/yyyy):	14b. Authorised Signature:	14c. Certificate /Approval Ref No.:
			UK.145.00846
13d. Name:	13e. Date (dd/mm/yyyy):	14d. Name:	14e. Date (dd/mm/yyyy):
		Bartosz Pachulski	27/Jun/2019

This certificate does not automatically constitute authority to install the item(s).

Where a user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Avia Technique

SAE Aero Safety Group

Avia Technique Ltd.
Unit 1,3,4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W201911063

Date Printed: 21/06/2019

Page: 1

To:
Burwood Aviation Supplies Ltd
8 Bessemer Close
Burwood House
Verwood, Dorset BH31 6AZ
United Kingdom

Ship To:
Burwood Aviation Supplies Ltd
8 Bessemer Close
Burwood House
Verwood, Dorset BH31 6AZ
United Kingdom

Reference: 111546
Date Received: 20/06/2019
Part Number: 8915-1-14
Description: Oxygen Cylinder Assembly
Serial Number: COJ20076

Customer Remarks:

Overhaul

Results from inspection:

Unit requires Overhaul

DOM: 12-2007

Corrective actions:

Overhaul with ref to the correct CMM

Refill with Aviation/Breathing Oxygen compliant with MIL-PRF-7210 Specification

Inspection report generated by: Callum Soane