

1. Approving Civil Aviation Authority/Country: FAA / UNITED STATES

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number: PAI258917

4. Organization Name and Address: **Perform Air International, Inc.** · 463 S. Hamilton Ct. · Gilbert, AZ 85233

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	DRAIN VALVE	4631-100	1	58917PAI	Inspected and Tested

12. Remarks: **Work Order: 258917**
Mechanic Performing Work: Mariah Carlos
Work Completion Date: 8/20/2019

Technical Data: 38-31-10
 Cust Part Number: N/A
 OEM: MONOGRAM S. STEMS
 Cust Serial Number: N/A

Work accomplished IAW CMM 38-31-10 Rev. 6, dated 8/19/2010. Assigned S/N: 258917PAI. Per customer request, AD review accomplished.


Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the article is considered ready for release to service under EASA Part 145 approval no. EASA.145.4741.

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and approval condition for safe operation
 Non-approved design data specified in Block 12

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12

Certifies that unless otherwise specified in block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
			IS3R590L
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
		Michael Mollman	20 Aug 2019

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certificate issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Perform Air International, Inc.
463 South Hamilton Court
Gilbert, Arizona 85233
Tel. (480) 610-3500
Fax. (480) 610-3501



Date: 8/20/2019

FAA Repair Station IS3R590L

EASA Repair Station EASA.145.4741
CAAC Repair Station F00100571

Customer Information

Customer Code: EN014 Customer Name: Burwood Aviation Supplies Ltd
Warranty Terms for Repair: 12 Months Warranty Terms for Overhaul: 18 Months

Information from Repair Order / Purchase Order

Repair Order#: 111806
Mfg P/N from RO/PO: 4631-100 Mfg S/N from RO/PO: NSN
Nomenclature: DRAIN VALVE RO/PO Disposition: Test Warranty Request: No
Reason for Removal: Per customer request 8/19/2019 please assign a S/N. Test, RR: Test and Re-cert. Unit is SV with an old tag- needs re-cert. No PMA or DER repairs are allowed without acceptance.

Information for Part Received

Work Order#: 258917 Mfg P/N Received: 4631-100 Mfg S/N Received: UNK
Date Received: 8/16/2019
Fault Confirmed: No Normal Wear and Tear: No Any Unrelated Faults: No
Preliminary Inspection: AD review accomplished. See customer discrepancy. Dirty. Inspected and tested unit IAW CMM 38-31-10 Rev. # 6, dated 8/19/2010. Unit tested serviceable.
Warranty Granted: None
Warranty Comments: N/A

Information for Part Shipped Back

Mfg P/N Out: 4631-100 Mfg S/N Out: 258917PAI
Customer P/N Out: N/A Customer S/N Out: N/A
Status: Inspected and Tested Manual Ref#: 38-31-10
Teardown Procedure: N/A
Repair Procedure: N/A- Per customer request 08/19/2019 please assign a S/N 258917PAI.
Test Procedure: Bench tested unit IAW CMM 38-31-10 Rev. # 6, dated 8/19/2010. No faults found.
Modifications Incorporated: N/A

Mechanic: Mariah Carlos
Certificate #: Pending
Date Repaired: 8/20/2019

Inspector: Michael Mollman
Date Inspected: 8/20/2019

