

1. Approving Competent Authority / Country  
CAA/The Netherlands

2. **AUTHORIZED RELEASE CERTIFICATE**  
EASA FORM 1

3. Form Tracking Number  
670312



**AAR Aircraft Component Services**  
Kruisweg 705, 2132 ND Hooftdorp, The Netherlands  
P.O. Box 2130 AB Hooftdorp, The Netherlands  
Tel: 31(0)206552222 Fax: 31(0)206554777

4. Organization Name and Address:  
5. Work Order/Contract/Invoice  
111879

6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status/Work
1	MODE CONTR PNL	4068250-901	1	99080191	INSPECTED / TESTED

12. Remarks  
Item maintained in accordance with Component Maint. Manual 22-55-02, Revision 5, dated 16-Oct-2015.  
No cycle data available.

The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under FAA certificate No. QT1Y438K.

Mod. status: A.

13a. Certifies the items identified above were manufactured in conformity to:  
 approved design data and are in a condition for safe operation  
 non-approved design data specified in block 12

14a.  Part-145, A.50 Release to Service.  Other regulation specified in Block 12  
 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part 145 and in respect to that work, the items are considered ready for release to service.

13b. Authorized Signature	13c. Approval/Authorization Number	14b. Authorized Signature	14c. Certificate/Approval Ref. No.
			NL. 145. 1133
13d. Name	13e. Date (dd mmm yyyy)	14d. Name	14e. Date (dd mmm yyyy)
		M. de Boer	20 SEP 2019

**USER/INSTALLER RESPONSIBILITIES**  
 The certificate does not automatically constitute authority to install the item(s).  
 Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.  
 Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



# Shop Record

Aircraft Component Services  
Kruisweg 705, 2132ND  
Hoofddorp, the Netherlands

Customer : Burwood Aviation Supplies Ltd

Job ref : 670312

Partnumber : 4068250-901

Serial number : 99080191

Description : MODE CONTR PNL

R/O : 111879

Type :

Date R/O : 30-AUG-19

NSN :

Date in : 02-SEP-19

Manufacturer : Honeywell Inc. (Sperry)

Complaint : Failed on fit, PLT selector digital counter hunting and altitude selector intermittent skips digits.

Requested action : Repair

Incoming inspection : Complaint not confirmed.

Visual condition : OK

Findings: None

Work performed : Inspected / Tested

Actual work : Unit has been tested and found serviceable.

Note: If any parts were replaced, a record of parts used as replacement is being held at AAR.  
This record is available upon request.

Mod. status : A.

### Remarks :

Item maintained in accordance with Component Maint. Manual 22-55-02, Revision 5, dated 16-Oct-2015.  
No cycle data available.

Shop Manager :

H.A. Pauw

20-Sep-2019

### Certificate of Conformance

(only signed if released under non-civil aviation regulation)

This is to certify that the services to the component as described above conform in all respects to the specification(s), drawings and order relative thereto and that the component has been inspected and tested i.a.w the conditions and requirements of the order and was found airworthy for return to service.

Authorized :  
Signature

This is to certify that within the provisions of STANAG 4107, AQAP2070 and the agreed RGQA, the services identified above have been subject to Government QA and are considered to comply with the provisions of the applicable contract.

GQAR :  
Signature