

1. Approving Civil Aviation Authority/Country: **FAA/United States**

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number: **111487**

4. Organization Name and Address: **ICON AEROSPACE, LLC.
2617 EXECUTIVE POINT DR.
MONROE, NC 28110**

5. Work Order/Contract/Invoice Number: **W117198**

6. FAA Repair Station : 681R700B
EASA Reference : EASA.145.6295
Pn: 704-821-4266 Fax: 704-821-4286

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	INTERPHONE, HANDSET/CRADLE	5483-1-8	1	1524	REPAIRED

12. Remarks: **REPAIRED** In Accordance with CMM 23-30-23 Rev.: 1 Date: MAR/05/2007
The above specified unit was manufactured by: AVTECH CORP.

FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W117198

COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADS):
N/A
COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs):
N/A

Certifies that the work specified in blocks 11/12 was carried out in accordance with EASA Part-145, and in respect to that work, the component is considered ready for service under EASA Part 145 Approval Number EASA.145.6295

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.

Non-approved design data specified in Block 12

13b. Authorized Signatures:

13c. Approval/Authorization No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12.
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

14b. Authorized Signature:

14c. Approval/Certificate No.:

14d. Name (Typed or Printed): **ALEXSANDER GARCIA**

14e. Date (dd/mm/yyyy): **19/Sep/2019**

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



FAA REPAIR STATION 681R700B
 EASA REFERENCE EASA.145.6295
 2617 EXECUTIVE POINT DR.
 MONROE, NC 28110
 Ph: 704-821-4266 Fax: 704-821-4286
 Email: sam@iconaerospace.com

WORK ORDER

W117198

Date Rcvd : 12/Jun/2019

TEARDOWN REPORT

BURWOOD AVIATION SUPPLIES, LTD.
 Burwood House
 8 Bessemer Close,
 Ebblake Industrial Estate
 Verwood, Dorset.
 ENGLAND BH31 6AZ

Cust RO#: 111487
 P/N: 5483-1-8
 S/N: 1524
 Desc: INTERPHONE, HANDSET/CRADLE
 Mfgr: AVTECH CORP.

Manual Loc: AT-016
 ATA: 23-30-23
 Rev: 1 Rev Date: 05/Mar/2007
 Tag Date: 19/Sep/2019

Contact: DARON GOLDING
 Contact Ph: 44-1202-825434
 Contact Fax: 44-1202-823416

Reason Removed: UNIT RECEIVED FOR REPAIR AS PER O.E.M SPEC'S

FINDINGS

RECEIVING INSPECTION:

VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND. UNIT RECEIVED MISSING MAGNETIC HOLDER AND CRACKED INFO PLATE.

PRELIMINARY INSPECTIONS:

TESTED UNIT. FAILED FUNCTIONAL TEST.

HIDDEN DAMAGE:

NONE

CONTINUED INSPECTION:

TESTED. UNIT HAS A DAMAGED FRONT AND REAR HOUSING AND PANEL. MISSING STRIKE PLATE. DISASSEMBLY IS REQUIRED.

CORRECTIVE ACTION: UNIT CONDITION REPAIRED

REPLACED PART(S) AS REQUIRED. CLEANED AND REASSEMBLED UNIT. TESTED AS PER O.E.M SPEC'S.

SB's, AD's, EO's and RMK's:

NONE

CERTIFICATION

Service Performed: REPAIRED

MODIFIED TO:

PARTS AND MATERIALS

QTY	PART NUMBER	DESCRIPTION	COND
1	5283-28	STRIKE PLATE	NE
1	5483-53-4	EDGELIT PANEL	SV
1	AD-5483-23-3	FRONT HOUSING	NE
1	AD-5483-24-3	REAR HOUSING	NL

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY: ALEXSANDER GARCIA

DATE: 19/Sep/2019